

Spectra Material- Washing Recommendations

Gloves knit or woven from Spectra materials can be hand or machine washed using soap or detergent.

Spectra gloves may be bleached or soaked in other sanitizing agents.

Washing temperatures should not exceed 90° C.

Drying temperatures should not exceed 70° C, with drying time not to exceed 10 minutes, or excessive shrinkage can occur.

As Spectra gloves are not water absorbent, it is recommended that the gloves be dried separately from more absorbent materials such as cotton or other absorbent fibers. This practice reduces drying time.